## **ARROW ADVISES**





BUCKETS & VS SLIPSTOP®





| THE PROBLEM   | THE SLIPSTOP® SOLUTION   |
|---|--|
| Multiple buckets & wet floor signs look untidy                                      | <ul> <li>Consolidates signage &amp; equipment into one unit</li> <li>Water collected out of sight, improving image</li> </ul>  |
| Wet floor signs are easily obscured or knocked over                                 | <ul> <li>'360' design means slip hazards are always visible</li> <li>Robust, sturdy unit - not easily knocked over</li> </ul>  |
| Multiple leaks require multiple<br>buckets/signs - increasing<br>equipment required | <ul> <li>Wide funnel design maximises collection area</li> <li>Place multiple SlipStops together to further increase coverage</li> <li>Easy storage &amp; assembly: SlipStop® 65 flatpacks; SlipStop® Cone stacks</li> </ul> |
| Buckets are easily<br>knocked over, creating<br>additional slip risk                | <ul> <li>Wide funnel safely &amp; efficiently collects<br/>water with no drips</li> <li>Liners absorb collected water, eliminating spill risk</li> </ul>   |



Visit www.arrowcounty.com/slipstop or contact 01743 283600 to find out more

